

D/OP - SPB Photographic Evaluation Sheet

Division No. 1315 Evaluation Date 13 November 1956 Evaluation No. 97-56
 Camera / Lens Serial _____ Code Serial _____
 Magazine Serial _____

1. Shutter Operation	Good
2. Film Metering	Slightly off
3. Film Loading	Good
4. Vacuum Failure	---
5. Slack Operation	Good
6. Overlap	55% average
7. Exposure Counter Operation	---
8. Data Transfer (Image Quality)	Poor to good
9. Static Electricity	None observed
10. Vignetting	None observed
11. Pinholes	None observed
12. Scratches	Minor thru-out
13. Tearier (VIB)	None observed
14. Pressure Straks	None observed
15. Water Spots	None observed
16. Density	Medium to dark
17. Contrast	Medium to low
18. Apparent Resolution	Poor to good
19. Apparent Granularity	Medium
20. Flare	None observed
21. Suitability for MI	Poor to good

DOCUMENT NO. _____
 NO CHANGE IN CLASS. **X**
 DECLASSIFIED
 CLASS. CHANGED TO: TS S O
 NEXT REVIEW DATE: **2012**
 AUTH: RH 102
 DATE: **3 MAR 1982** REVIEWER: **064540**

Remarks: Apparent double image in center portion of frames.