




*VARIOUS PHOTOS OF  
SCANNER-RECORDER*





Another View showing  
system in Hatch

B 6 1 4 6 8 2

Notice when H.E. hoses  
are clamped and where  
Cables are tied using  
parachute Cord. This  
is very important.

B 6 1 4 6 8 2



System in Hatch, showing  
the routing of cables and  
H.E. Hoses.

B 6 1 4 6 8 2

[Faint, illegible text or markings in the bottom right quadrant]

D 5 1 5 4 7 3


*VARIOUS PHOTOS OF  
ELECTRONIC PACKAGES  
INSTALLED IN AIRCRAFT*




*This is a view from  
airplane looking up into the  
cove bay. Bottom cover just  
happened to be off of electronics  
box, when pic was taken*

*Top View Mounted in  
Aircraft*

*Top View Mounted in  
Aircraft*



ENLARGEMENT OF RURAL AZER-DATA ANNOTATION CHECK AT RIGHT



ENLARGEMENT OF METROPOLITAN AREA