

Page Denied

Next 1 Page(s) In Document Denied

SECRET

63

(Security Classification)

25X1

(See inside cover)

CONTROL NO. Z-15352/83

NPIC/PEG (10/83)

COPY _____ OF _____

ROUTING			
TO:	NAME AND ADDRESS	DATE	INITIALS
1			
2			
3			
4			
	ACTION	DIRECT REPLY	PREPARE REPLY
	APPROVAL	DISPATCH	RECOMMENDATION
	COMMENT	FILE	RETURN
	CONCURRENCE	INFORMATION	SIGNATURE
REMARKS:			
FROM: NAME, ADDRESS, AND PHONE NO.			DATE




Warning Notice

Intelligence Sources or Methods Involved

NATIONAL SECURITY INFORMATION

Unauthorized Disclosure Subject to Criminal Sanctions



SECRET

(Security Classification)

Warning Notice
Intelligence Sources or Methods Involved
(WNINTEL) or (D)

NATIONAL SECURITY INFORMATION
Unauthorized Disclosure Subject to Criminal Sanctions

DISSEMINATION CONTROL ABBREVIATIONS

NOFORN-	Not Releasable to Foreign Nationals
NOCONTRACT-	Not Releasable to Contractors or Contractor/Consultants
PROPIN-	Caution-Proprietary Information Involved
ORCON-	Dissemination and Extraction of Information Controlled by Originator
REL . . .	This Information has been Authorized for Release to . . .

SECRET



25X1

(c) NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER

Page 1 of 1

Attachment to Z-15352/83
NPIC/PEG (10/83)
2-PART GRAPHIC

Copy _____


CORINTO PORT FACILITIES, NICARAGUA



25X1

1. SIGNIFICANCE: SIGNIFICANT DAMAGE HAS OCCURRED TO THE PETROLEUM STORAGE AREA  (SWN)

25X1

2. REMARKS: AT LEAST ONE LARGE STORAGE TANK, ONE SPHEROIDAL TANK, AND TWO SMALLER TANKS HAVE BEEN DESTROYED. ONE OF THE SMALLER TANKS APPEARS TO BE SMOLDERING, AND PROBABLE FIRE FIGHTING EQUIPMENT IS ON THE ROAD NEARBY. PART OF THE FENCE AROUND THE STORAGE AREA HAS ALSO BEEN DESTROYED. AT LEAST ONE MEDIUM TANK AND THREE SMALLER TANKS IN THE SAME AREA APPEAR TO HAVE SUSTAINED SOME DAMAGE. THREE MEDIUM TANKS IMMEDIATELY WEST OF THIS AREA APPEAR TO HAVE SUSTAINED MINOR DAMAGE. ONE PROBABLE STORAGE BUILDING, ONE PROBABLE PUMP SHED, AND ONE SMALL SHED HAVE ALSO BEEN DESTROYED. A LONG STORAGE BUILDING NEAR THE SPHEROIDAL TANK MAY ALSO HAVE SUSTAINED SOME DAMAGE. PROBABLE POL TRUCKS AND OTHER VEHICLES ARE OUTSIDE THE FACILITY. HEAVY HAZE PRECLUDES AN ACCURATE ASSESSMENT OF ADDITIONAL DAMAGE; HOWEVER, NO DAMAGE IS DISCERNIBLE TO THE POL PIER, THE LARGE CRANE, OR TO THE PORT FACILITIES. TWO UNIDENTIFIED MERCHANT SHIPS HAVE DEPARTED THE PORT  (SWN)

25X1

3. , COORDINATES 12-28-50N 087-10-07W

25X1

25X1



These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue.



25X1

WARNING NOTICE
Intelligence Sources
and Methods Involved

SECRET



25X1